

Series

Fingerprint Employee Time Clock User Guide (V1.0)



Feature

- USA TI 300MHz high speed processor
- USA BioNano core fingerprint algorithm of high speed and stability
- New generation fully sealed, waterproof and dustproof fingerprint sensor
- User name display and human voice prompt
- Realtime data transfer and WEB online tracking
- A20: Standard USB, USB pen drive
A300: Standard USB, USB pen drive and TCP/IP
- Identification method: FP, ID+FP, ID+PW,
- Fingerprint capacity: 2000
- Record capacity: 50000
- Identification speed: <0.5 second
- Size: 200mm(w)*140mm(h)*38mm(d)

Content

Safety Precautions.....	4
Glossary.....	5
Illustration for placing fingerprint.....	6
Packing List.....	7
Appearance.....	8
System Menu.....	11
User--Enroll(Fingerprint).....	14
User--Enroll(Password).....	15
User--Enroll(Card).....	16
User--Delete.....	17
User--Verify Mode.....	18
User--Admin Setup.....	19
User--Admin Clear.....	20
Setup--System.....	22
Setup--System--Net.....	24
Setup--Log Setup.....	25
Setup--Hardware Test.....	26
USB Flash--Record Backup.....	28
USB Flash--User Backup/Recovery.....	29
System Info.....	30

Safety Precautions

- Please read it carefully first of all;
- Don't install the terminal under direct light, humid, dusty or dirty environments;
- Don't install the terminal near the magnetic field;
- Don't install the terminal near the heating device;
- Don't sprinkle liquids (water, drink, chemical) on the terminal;
- Always keep the surface of the terminal clean;
- Clear the terminal with a towel when there is water on the surface;
- Don't break the terminal;
- Don't press two keys at the same time;
- Don't take down, repair or change the terminal without authorization;
- Don't allow children to touch the terminal;
- This terminal is only used for fingerprint verification, don't use it for other purposes;
- If in doubt please contact the local distributor;

Glossary

■ Administrator

- It is a special user who has the authorizations of setting the terminal system settings and user information. The admin can add or delete the users, and the admin also can change the system settings of the terminal.

■ 1:1 Identification

- If it is 1:1 identification mode, the user has to input the user ID firstly, then verify the fingerprint or enter the password to make identification.

In this mode, the fingerprint sensor on the fingerprint template will identify with the one of the special user ID.

■ 1:N Identification

- Under 1:N mode, the user need not enter any user ID. Just need place the fingerprint on the fingerprint sensor . The terminal will automatically identify this fingerprint with the ones of all users registered in inside database.


■ Fingerprint Enrollment

- It is the process to capture the fingerprint image features got from the fingerprint sensor and save the inside memory into the terminal.


Illustration for placing fingerprint

- **Correct method:**

Straighten finger and place it flatly on the sensor, and make the fingerprint maximally cover the sensor.




Place finger in the center of the sensor.




Place finger flatly and smoothly on the sensor.


- **Incorrect method:**




Move finger before the backlight of sensor is off.




Place finger away from the center of the sensor.




Tilt sensor.



Take off finger during the process of fingerprint verification.



Use fingertip.



Slide finger during the process of fingerprint verification.

Packing List



A Series Fingerprint Employee Time Clock



USB Cable (1.5 meters)



USB Power Adapter




Software CD



Quick Guide


Appearance

■ Front



Appearance

- Back



For Administrator——Basic Functions





Manage employees' information.
Main functions:
Register users, delete users,
add/delete admin and so on.

System Menu

- Please press [M] to enter system management menu under initial state.
 - Since anyone can enter the terminal's management menu under initial state by pressing [M], we suggest you set the admin shortly after installation of the terminal.
 - The method of registering admin is the same for common employees. Please refer to "User Enrollment" and "Admin Setup" instructions.

- Verify the admin to enter the system management menu.
 - There are two ways to verify admin:
 1. Fingerprint verification: Let the person who is expected to be the admin place his/her finger on the sensor to verify.
 2. Password verification: Enter the admin's ID and password, press [OK] to confirm.
Enter the system management menu after the admin verification is successful.


- If the admin verification is OK, it will enter the system management menu.



System Menu

Menu list:

- User: for example: [Enroll], [Delete], [Verify Mode], [Admin Setup], [Admin Clear].
- Setup: [System], [Log Setup] and [Hardware Test].
 [System] includes: system time, language, network parameter, fingerprint verification precision, system voice volume, dormancy time and so on.
 [Log Setup] includes: clock in/out records storage alarm and fingerprint repeat clock in/out time period
 [Hardware Test] includes: keypad, LCD, voice, fingerprint sensor, flash test.
- System info: Show existing users amount, fingerprints amount, records amount, firmware version.



- Press [IN/←] or [OUT/→] to select a corresponding submenu and press [OK] to confirm.
- Enter submenu, press [IN/←] or [OUT/→] to select different options for setup.
 - After setup, press [C] turn to save submenu. Press [OK] to save, or press [C] to cancel, and either of the operation will return to the previous menu.

System Menu






- Press [C] to exit the system management menu.
 - To ensure safety, the system management menu will automatically return to the default menu if no operations in a certain period.

User--Enroll (Fingerprint)

- Enter the system management menu. Select [User]-[Enroll]. Press [OK] to enter the enroll menu. Enter employee's ID and press [OK] to register employee.
 - Press [OUT/→] to select [FP 1] or [FP 2]. Press [OK] to start fingerprint enrollment. Press [OK] to save and return to the enroll menu.

- Place finger on the sensor correctly. Please refer to <The way to enroll a fingerprint>.
 - You need to enroll one fingerprint twice. Please enroll fingerprints according to LCD prompt.
 - If the second fingerprint enrolled is different from the first one, or the way you place finger is incorrect, it will prompt "Please try again".
 - If the fingerprint is existed, it will prompt "Fingerprint repeated". Please enroll another fingerprint.

- You can continue to enroll employees one by one. Or press [C] to exit.



User--Enroll (Psssword)

- Enter [Menu], select [User] and press [OK] to [Enroll] interface.
Input employee's ID and press [OK] to register employee.
 - Press [OUT/→] to select [Password], and press [OK] to enroll.
 - Input password(1 to 6 numbers) and press [OK] to confirm.
 - Input password again,and press [OK] to confirm.
 - Press [OK] to save password.

- Press [C] to exit to [Enroll] interface to continue, or press [C] to back to defult interface.

Enroll

ID 008101

Esc-C Set-OK

Enroll

FP 1/2

Password /Card

Esc-C Set-OK

Pass Enroll

PWDID *****

Esc-C Set-OK

Pass Enroll

PWDID *****

Confm *****

Pass Enroll

008101-P

Cancel-C Sav-OK

User--Enroll (Card)

- Enter [Menu], select [User] and press [OK] to [Enroll] interface.
Input employee's ID and press [OK] to register employee.
 - Press [OUT/→] to select [Card], and press [OK] to enroll.
 - Swipe the employee's card, and the system will get card number and enter save interface.
 - Press [OK] to save password.

- Press [C] to exit to [Enroll] interface to continue, or press [C] to back to default interface.

Enroll

ID 008101

Esc-C Set-OK

Enroll

FP 1/2

Password/Card

Esc-C Set-OK

Card Enroll

Punch Card!

Card Enroll




008101-C

Cancel-C Sav-OK

User--Delete

- When employees resign, we need delete the employee's information in the terminal. Enter the management menu.
Select [User]-[Delete] press [OK].
 - Enter the employee's ID and press [OK], the system will prompt again whether to delete, press [OK] again to confirm delete the employee information.
 - Continue to delete other employees after deleting successfully, or press [C] to back to the default interface.

- Notice: Please caution with the action. All deleted information including employee's fingerprint, password, attendance records can not be recovered.
 - If deleted by mistake, please connect with the PC and upload the employee information which has been backed up before to recover the employee information.



User--Verify Mode

- Enter the management menu. Select [User]-[Verify Mode] press [OK] to enter the setting interface.
 - Press [OUT/→] to select employee or press [OK] to input user ID.
 - Press [OK] to enter setting interface.
 - Set employee's verify mode through [OUT/→], there are three modes: [ANY], [PW+FP] and [ID+FP].
 - Then press [OK] to save this setting.

User ▼

Enroll

Delete

▶Verify Mode

Verify Mode ▼

Esc-C Set-OK

Verify Mode

ID 008101

Esc-C Set-OK

Verify Mode

008101 PW+FP

Yes-OK

Verify Mode





008101 PW+FP

Cancel-C Sav-OK

User--Admin Setup

- In the management interface, select [User]-[Admin Setup] press [OK].
 - Press [OK] to enter the admin user ID and press [OK] to confirm, the system will prompt whether to set user as admin. Press [OK] to confirm and press [C] to cancel.

- It asks for the admin verification before entering the system management menu if you set a admin in the terminal.



User--Admin Clear

- In the management interface, select [User]-[Admin Clear] press [OK].
 - Press [OUT/→] to select the admin ID press [OK] to confirm.
 - The admin ID will be showed on the LCD press [OK] to confirm.
 - The system prompt whether delete the admin. Press [OK] to confirm deletion. Press [C] to cancel.

- Notice: In the admin delete interface, press [OK] to enter the user ID interface directly, then enter the ID to delete admin.

```
Admin Clear
ID          008101
▶ ID        008102
Esc-C      Clr-OK
```

```
Admin Clear

ID          008102
```

```
Admin Clear

          008102
No-C      Yes-OK
```

```
Admin Clear
▶ ID          008101
Esc-C        Clr-OK
```

For Administrator---Advanced Functions



Set the terminal parameters,
include:
System Setting, Record Setting
Hardware Test and so on

Setup--System

- In the management interface, select [Setup]-[System], then press [OK] to enter the sub-menu.

Dev ID

- Terminal's serial number.

Time





- Set system time, time format displays as "YY-MM-DD H:M".
- Select [Time], then press [OK].
- Press [OK] to change the date and time one by one.
- Press [C] to enter save interface and press [OK] to confirm.

Language

- Set language.
- Select [Language], then press [OK]. Press [IN/←] or [OUT/→] to select the language, then press [OK].
- Press [C] to enter save interface and press [OK] to confirm.

Precision

- Set terminal fingerprint comparison precision.
- 0-[Low], 1-[Normal], 2-[High].
- Select [Precision], then press [OK]. Press [IN/←] or [OUT/→] to set the precision value and press [OK].
- Press [C] to enter save interface and press [OK] to confirm.



Setup--System

Volume




- Set the terminal voice volume. 0-[mute], 5-[Max].
- Select [Volume], then press [OK]. Press [IN/←] or [OUT/→] to set the volume value and press [OK] to confirm.
- Press [C] to enter save interface and press [OK] to confirm.

Auto Off

- Set the time duration from the last operation to the dormant state.
- No-[Not Off], 250-[Max Time].
- Select [Auto Off], then press [OK]. Press [IN/←] or [OUT/→] to set [NO] or auto off time and press [OK] to confirm.
- Press [C] to enter save interface and press [OK] to confirm.

Auto Update

- Auto update means the previous lower quality fingerprint template will be automatically replaced by the new higher quality one during fingerprint verification.
- Select [Auto Update], then press [OK]. Press [IN/←] or [OUT/→] to select [Yes] or [NO] and press [OK] to confirm.
- Press [C] to enter save interface and press [OK] to confirm.



Setup--System--Net

- Enter the system management menu, Select [Setup]-[System]-[Net]. Press [OK] to enter the sub-menu.

This function main includes [IP Address], [Subnet Mask], [MAC Address] and [Gateway IP] settings.

- Press [OUT/→] to select [IP Address] or [Subnet Mask] or [MAC Address] or [Gateway IP]. Press [OK] to enter modify interface.
- Press [OK] to select the parameters, and press [IN/←] or [OUT/→] or number key to modify
- Press [C] to enter save interface
- Press [OK] to confirm and return to the [Net] menu.

Net ▾
▶ IP Address
Subnet Mask
MAC Address

IP Address
192 . 168 . 000 . 218
Set-C Next-OK

Subnet Mask
255 . 255 . 255 . 000
Set-C Next-OK

MAC Address
051 . 247 . 188 . 066
084 . 215
Set-C Next-OK

Gateway IP
192 . 168 . 000 . 001
Set-C Next-OK

Setup--Log Setup

- In the management interface, select [Setup]-[Log Setup], then press [OK] to enter the sub-menu.

Log Alert

- The terminal will alarm when the memory capacity is less than the [Log Alert] value.
- [No]-Not alarm, Max. value 5,000.
- Select [Log Alert], then press [OK]. Press [IN/←] or [OUT/→] to set [NO] or input the warning records value and press [OK] to confirm.
- Press [C] to enter save interface and press [OK] to confirm.

Re-Verify

- Set a period during which time the system only save the first successful record and do not save the repeated records.
- [No]: Disable the function; Max. value is 250 min.
- Select [Re-Verify], then press [OK]. Press [IN/←] or [OUT/→] to set [NO] or enter the value and press [OK] to confirm.
- Press [C] to enter save interface and press [OK] to confirm.

```
Log Setup
▶Log Alert      1000
Re-Verify      NO
```

```
Log Setup
▶Log Alert      3000
Re-Verify      NO
```

```
Log Setup
Log Alert      3000
▶Re-Verify     NO
```

```
Setup
                Save?
No-C           Yes-OK
```

Setup--Hardware Test

- In the management interface, select [Setup]-[Hardware Test] and press [OK] to test Keypad, LCD, Voice, Sensor and Flash.

Keypad

- Test the keypad.
- Select [Keypad] and press [OK].
- Press any key on the keypad. If LCD shows the same, the keypad is good.

LCD






- Test the LCD.
- Select [LCD] and press [OK].
- Press [OK] to start test.

Voice

- Test the terminal voice.
- Select [Voice] and press [OK].
- Terminal auto tests 1-17 voices.

Sensor

- Test the sensor's luminance.
- Select [Sensor] and press [OK] .
- The luminance value will be changed according to the environment.



Setup--Hardware Test

Flash

- Test the terminal flash memory.
- Select [Flash] and press [OK] .
- Notice: This test will delete all the data in the flash memory and then check it.
- Please backup the data before this operation.

Step 1

Erase All Data
Continue?

Esc-C

Yes-OK

Step 2

Check... 100%

Flash

Flash OK!

Esc-C

USB Flash--Record Backup






- Connected U disk to terminal, press [M] to enter the management menu, select [USB Flash] and press [OK].

New Rec. Backup

- Download new T&A records to U pan drive.
- Press [OUT/→] to select [New Rec. Backup], press [OK] to download the new records.
- After back up process bar shows 100%, press [C] to exit and back to upper menu.
- New record file is BAK.KQ located in G:\00000001. 'G' is the disk name on PC of U pen drive. '00000001' is T&A machine serial number.

All Rec. Backup

- Download all T&A records to U pan drive.
- Press [OUT/→] to select [All Rec. Backup], press [OK] to download all records.
- After back up process bar shows 100%, press [C] to exit and back to upper menu.
- The record file is BAK.KQ located in G:\00000001.
- Prompt: if you backup new records firstly, recommend to save new record file to local pc. Else it will be replaced with all records file.



USB Flash--User Backup/Recovery

User Backup

- Download employee's records saved in device to U pen drive.
- Press [OUT/→] to select [User Backup], press [OK] to download the employee information.
- After backup process bar shows 100%, press [C] to exit and back to upper menu.
- The backup file is BAK.YG and BAK.ZW located in G:\00000001.

User Recovery

- Upload employee's information saved in U pen drive to terminal.
- There are two ways to recover employee information:
 1. Copy BAK.YG and BAK.ZW to root directory, then plug U pen drive into time attendance machine and start user recovery.
 2. Export employee information to U pen drive through U flash management software, then repeat step 1.
- Press [OUT/→] to select [User Recovery], press [OK] to recovery all records.
- After recovery process bar shows 100%, press [C] to exit and back to upper menu.

USB Flash ▼
New Rec. Backup
All Rec. Backup
▶ User Backup

User Backup
Backup... 0%

New Rec. Backup
OK! 100%
Esc-C

USB Flash ▼
▶ User Recovery

User Recovery
Backup... 0%

User Recovery
OK! 100%
Esc-C

System Info

- In the management interface, select [System Info] and press [OK] to check the terminal information.

User • Registered user number. Maximum 2,000 users.

FP • Registered fingerprint number. Maximum 2,000 fingerprints.
• Press [OK] to view the number of users who registered a password.

Log • The time attendance logs. Maximum 50,000 records.

FirmVer • The firmware version.

- Press [C] back to the management interface.

MENU
▶ System Info

System Info ▼
▶ User 2000
FP 2000
Log 50000

System Info ▼
User 1000
▶ Password 500
Log 15000

System Info ▲
▶ FirmVer b1.15.00

ANVIZ

Invent • Trust

Anviz Biometric Tech. Co., Ltd.

EMAIL: sales@anviz.co.uk

Technical support

TEL: 0845 095 8072

EMAIL: support@anviz.co.uk

WEBSITE : www.anviz.co.uk